Form 3160 (June 1990	DEPARTMENT	D STATES OF THE INTERIOR ND MANAGEMENT	IE INTERIOR		OPY FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993	
	BOREAU OF LA	ind management		5. Lease (Designation and Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals				6. If Indiar	n, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE				7. If Unit or CA, Agreement Designation		
1. Type of Well Gas Gas					Lower S A Unit Sec. 31	
Well Other				8. Well Na	-Todd 3111 # //	
2. Name of Operator Saga Patroleum						
Saga Petroleum 3. Address and Telephone No.				9. API We	11 NO. 141-70173	
415 W. Wall, Suite 1900, Midland, TX. 79701				10. Field e	and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Tod	d Lower San Andres	
2120 FSL & 2023 FWL Sec. 31 T7S R36E				11. Count	y or Parish, State	
					Roosevelt	
12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
	TYPE OF SUBMISSION	TYPE OF ACTION				
	Notice of Intent	X Abandonm	ent	Chan	ge of Plans	
		Recompleti	on	New	Construction	
	Subsequent Report	Plugging Ba		·	Routine Fracturing	
	Final Abandonment Notice	Casing Rep		·	r Shut-Off	
		Altering Ca	ទាល	<u> </u>	ersion to Injection se Water	
				(Note: Repor	nce vectors tresults of multiple completion on Well r Recompletion Report and Log form.)	
4. Cut e 5. Spot 6 Spot	ft. plug @ 2035 - 1935. and pull 5 1/2 +/- 1000;. t 100' plug @ 5 1/2 stub. Tag it 100 ft. plug @ 8 5/8 shoe (50 in 50 out) lace plug install dry hoe marker.	Bottom of shoe @ 331'. T	ag			
Signed	ry certify that the foregoing is true and correct			Date	08/16/00	
Signed	B- mtg- ze for Federal or State office use) by				08/16/00	

RECEIVED AUG 3 1 2000 BLM ROSWELL, NM

٠.