

UNIT STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Dry Hole</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>NM 044216-B</u>
2. NAME OF OPERATOR <u>FRANKLIN, ASTON & FAIR, INC.</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 1090, Roswell, New Mexico 88201</u>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) <u>At surface</u> <u>1980' FNL & 1980' FWL, Sec. 18, T. 8 S., R. 38 E.</u>		8. FARM OR LEASE NAME <u>Roden</u>
14. PERMIT NO.		9. WELL NO. <u>1</u>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <u>4002.9</u>		10. FIELD AND POOL, or WILDCAT <u>Bluitt-San Andres</u>
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 18-8S-38E, NMPM</u>
		12. COUNTY OR PARISH 13. STATE <u>Roosevelt New Mexico</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☒

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On March 30, 1970, this well was plugged and abandoned as follows:

Circulated hole with mud and spotted 25 sack plug through tubing across perforations on 4704' - 4744'. Pulled tubing, ran free point and shot 5 1/2" csg. at 1412'. Spotted 35 sack cement plug through 5 1/2" csg. at 1412'. Spotted 35 sack cement plug through 5 1/2" csg. in and out of 8 5/8" surface csg. set at 283'. Set 5 sack plug and marker at surface.

18. I hereby certify that the foregoing is true and correct

SIGNED Grant M. Smith

TITLE Geologist

DATE 4-2-70

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

NOTED

APPROVED

SEP 24 1970

*See Instructions on Reverse Side

GORDON

J. L. GORDON
ACTING DISTRICT ENGINEER

RECEIVED

SEP 20 1970

OIL CONSERVATION COMM.
HOBBBS, R. M.