

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

Nm 0556301

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal B

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

5 Prairie

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

30-85-36E

12. COUNTY OR PARISH 13. STATE

Roosevelt

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Read & Stevens Inc.

3. ADDRESS OF OPERATOR

P.O. Box 2126 Roswell NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FSL 660 FEL

30-85-36E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4124.3 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANE

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Set 200' cmt plug from 6380' to 6580'

Set 200' cmt plug from 6380' to 6580'

Cut and pull 5 1/2" csg from 5,000'.

Set 150' cmt plug @ 5,000'

Set 150' cmt plug @ 4195' (8 7/8" csg shoe)

Set 130' cmt plug @ 2800' (yates top)

Set 100' cmt plug @ 375' (Surface pipe shoe) Needs to be in behind 9" casing

Set surf plug, install DH marker. * 50 minimum

Use 9.0 #/gal mud laden fluid throughout.

18. I hereby certify that the foregoing is true and correct

SIGNED

John C. Moley Jr.

TITLE

Eng

DATE

6/24/91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

See file, BLN (5), LAND, ACT

*See Instructions on Reverse Side