

Form 31(0-5
(November 1983)
(Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Bluitt San Andres Unit Sec.19	
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		9. WELL NO. 4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter D, 660' FWL & 510' FNL		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.19, T8S, R38E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4010 GL		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PCLL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perms 4717'-37' (¹⁸10 SX) 140' cmt. plug 4734'-4599' Tag plug.
2. Cut and recover approximately 3000' of 5-1/2" casing
- * 3. Set 10 sx plug across TOC 130' cmt plug centered on 5 1/2" casing stub. Tag plug.
- ** 4. Set 10 sx plug across surface csg shoe @ 280' 345' 26 1/2 cmt plug 395'-295' Tag plug.
5. Set surface plug with marker. Minimum 50' cmt. surface plug.

API No. 30-041-20193

* additional plug: 120' cmt. plug, 2240'-2360'

** note: BLM records show 8 5/8" 24" casing set at 345'

18. I hereby certify that the foregoing is true and correct

SIGNED <u>Bonnie Husband</u>	TITLE <u>Administrative Assistant</u>	DATE <u>Jan. 28, 1994</u>
------------------------------	---------------------------------------	---------------------------

(This space for Federal or State office use)

APPROVED BY <u>approved as modified.</u>	TITLE _____	DATE _____
--	-------------	------------

*See Instructions on Reverse Side