

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLE
COPIES INSTRUCTIONS
Reverse Side

12-
10-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-00202

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Roger C. Hanks	8. FARM OR LEASE NAME Long Star
3. ADDRESS OF OPERATOR c/o Hobbs Pipe & Supply, Box 2010, Hobbs, N. M.	9. WELL NO. 1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit H, 1930' FNL & 660' FEL	10. FIELD AND POOL, OR WILDCAT South Pratt Field
14. PERMIT NO.	11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA 29-38-36E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Roosevelt N. M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	

(Other) _____
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Ran CIBP @ 9,508', w/35' cement on top.
2. Loaded hole w/mud-laden fluids.
2nd Set 25 sack plugs at 7500-7700 and 5200-5500 ft.
3. Shot pipe @ 3,620'.
4. Spotted a 35 sx plug @ 5 1/2" casing stub, 3,600'.
5. Spotted a 35 sx plug @ 2,300'.
6. Spotted a 50 sx plug in & out of 8-5/8 casing stub, 1,265'.
7. Spotted a 60 sx plug in & out of base of 13-3/8" surface pipe, 400/500'.
8. Spotted a 10 sx plug @ top & erected a 4" regulation marker.
9. Well was plugged and abandoned on 3/22/74.

18. I hereby certify that the foregoing is true and correct

SIGNED S. Saikin TITLE Agent DATE 4/24/74

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: