

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

AUG 25 11 13 AM '69

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
<b>E-8875</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>P &amp; A</b>	7. Unit Agreement Name
2. Name of Operator <b>Atlantic Richfield Company</b>	8. Farm or Lease Name <b>State "BL"</b>
3. Address of Operator <b>P.O. Box 1978, Roswell, New Mexico 88201</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM <b>West</b> LINE, SECTION <b>16</b> TOWNSHIP <b>8-S</b> RANGE <b>36-E</b> N.M.P.M.	10. Field and Pool, or Wildcat Dev. <b>So. Prairie (Ext) /</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4118' DF</b>	12. County <b>Roosevelt</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Drilled 8-3/4" hole to 13138' TD without encountering commercial hydrocarbons.**

**Well was plugged & abandoned by setting the following cement plugs:**

35 sk Class "E" cmt plug 13035-13125' (Top of Devonian @ 13064')  
25 sk Class "E" cmt plug 9485- 9550' (Top of Penn. @ 9517')  
25 sk Class "E" cmt plug 8965- 9030' (Top of Wolfcamp @ 8997')  
25 sk Class "E" cmt plug 7735- 7800' (Top of Abo @ 7762')  
25 sk Class "E" cmt plug 5445- 5510' (Top of Glorieta @ 5483')  
25 sk Class "E" cmt plug 4065- 4122' (bottom of 9-5/8" csg @ 4091')  
50 sk Class "C" cmt plug 1447- 1525' (half in & out of 9-5/8" stub @ 1475')  
25 sk Class "C" cmt plug 367- 398' (in & out of 13-3/8" shoe @ 381')  
10 sk cement plug in top of well.

**Shot off 9-5/8" casing w/jet casing cutter @ 1475', pld 47 jts of 9-5/8" csg. Heavy SGOE mud was used to spot all plugs. 13-3/8" surface casing was left intact. A dry hole marker was erected. Well was plugged & abandoned 8/19/69. We will notify you by letter when location is ready for inspection.**

**Received verbal permission for plugging program from Mr. John Runyan on 8/15/69.**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed

SIGNED O. D. Bretches TITLE Dist. Drlg. Supervisor DATE 8-21-69

APPROVED BY John W. Runyan TITLE Seal DATE JUL 15 1970

CONDITIONS OF APPROVAL, IF ANY: