Form (May	,	19	68	l 3)	
long.					

UNITED STATES SUBMIT IN TRIPLICA. 20 DEPARTMENT OF THE INTERIOR (Other Instructions, or reverse side)

		Form a Budget	Bures	ea. eu No	. 42-R	1424.
5.	LEASE	DENIGN	ATION	AND	BERIAL	NO.

GEOLOGICAL	SURVEY
------------	--------

	GEOLOGICAL SURVEY	n 11 15 10	N.11. 4030-B
SUNDRY (Do not use this form for Use "A	NOTICES AND REPORTS C proposals to drill or to deepen or plug b PPLICATION FOR PERMIT—" for such pi	ON WELLS TO THE DISTRIBUTION OF THE WINDS U. S. CEOLOGICAL MEXIC U. S. CEOLOGICAL MEXIC	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
		119 111 1 20K	7. UNIT AGREEMENT NAME
OIL A GAB OT	HER	JOS GICAL LEXIC	Υ
NAME OF OPERATOR	n a a a a a a a a a a a a a a a a a a a	CEOL VEM WILL	8. FARM OR LEASE NAME
	2	11. S. 028S, 1	1/13/17 600 T+4
The Maurice L. B	rown Company	O. HOPP	Will 693 Ltd.
ADDRESS OF OPERATOR			9. WELL NO.
Suite 200/Sutton	Place Bldg. Wichita atlon clearly and in accordance with any	, Kansas <u>47</u> 202	1
LOCATION OF WELL (Report loc See also space 17 below.)	ation clearly and in accordance with any	State requirements.*	10. FIELD AND POOL, OR WILDCAT
At surface	1		Vada Penn
љ "Р". 660' FS	Land 660' FEL		11. SEC., T., R., M., OR BLK. AND SURVEY OR ARBA
			Sec. 34, T-8-S, R-35
. PERMIT NO.	15. BLEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 18, STATE
	41771 KB. 41	1651 GR	beaute N.M.
. Cha	ck Appropriate Box To Indicate N	leture of Nieties Present on C	Dah D-4-
			₹
NOTICE OF	F INTENTION TO:	SUBSEQ	UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CABING
SHOOT OR ACIDIZE	ABANDON®	SHOOTING OR ACIDIZING	ABANDONMENT* X
REPAIR WELL	CHANGE PLANS	(Other)	
(Other)		(Note: Report results	of multiple completion on Well letion Report and Log form.)
DESCRIBE PROPOSED OR COMPLE proposed work. If well is nent to this work.)*	TED OPERATIONS (Clearly state all pertinen directionally drilled, give subsurface locat	t details, and give pertinent dates,	Including estimated date of starting any all depths for all markers and zones perti-
water to clear to 127 barrels of water Mixed and pumped Darrels of fresh	ged up PBCP Services, tubing. Total tally on 192 joints 2 7/8" he retainer. Set retater. Pressure tested 150 sacks of Class water. Pulled out of on top of retainer.	tainer at 6239'. ed tubing to 2500% 'H" neat cement. of retainer droppi	Loaded hole with #. Held O.K. Displaced with 33 ing 3 barrels of
5-25-80 Displaced hole whith tubing. We	ith 150 barrels of sa lded onto 5½" casing.	alt water gel mud. Rigged up hydra	. Pulled out of hole aulic jacks.
5-26-80 Vorked casing.			•
5-27-30 Shot 5½" casing Started laying d	in middle of joint at own 5%" cosing.	t 4000'. Circulat	ed pround 5%" easing.
8. I hereby testify that the fore	going is true and correct	District Engineer	
(This space for Federal or, S	ate office Vae		
APPROVE OF Sgd.) PE	TED W CHTSTS2		
CONDITIONS OF APPROVA			DATE
1			•
141	OV 5 1982		
1			

*See Instructions on Reverse Side

JAMES A. GILLHAM DISTRICT SUPERVISOR