

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC.
(Other instructions on
reverse side)

COPY TO

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MM-0234351

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Vada Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

34, 88, 36E

12. COUNTY OR PARISH

Roosevelt

13. STATE

N.M.

1. OIL ☒ GAS ☐ OTHER ☐
WELL WELL

2. NAME OF OPERATOR
R. R. Morrison

3. ADDRESS OF OPERATOR
c/o John L. Cox, I 408 W. Wall, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface **660' FN&L**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4009' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☒	ABANDONMENT* ☐
(Other) ☐	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 17-1/2" hole at 9:00 P.M. 10-16-69. Cemented 12-3/4" 34# casing at 400' w/375 sacks regular. Cement circulated. Plug down 10:30 A.M. 10-17-69. W.O.C. 24 hrs. and pressure tested casing w/600# for 30 min. Test O.K. Cemented 8-5/8" 24# & 32# casing at 4000' w/350 sacks. Plug down 3:30 P.M. 10-22-69. W.O.C. 24 hrs. and pressure tested casing w/1000# for 30 min. Test O.K. Cemented 4-1/2" 11.6# casing at 9859' w/460 sacks. Plug down 4:00 P.M. 11-15-69. W.O.C. 48 hrs. and pressure tested casing w/2000# for 30 min. Test O.K. Top cement behind casing by temperature survey 8090'. Perforated 9783-34' w/4 holes. Acidized w/2000 gal. 15% acid.

18. I hereby certify that the foregoing is true and correct

SIGNED *John L. Cox*

TITLE Agent

DATE 12-11-69

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

ACCEPTED FOR RECORD

DEC 15 1969

*See Instructions on Reverse Side. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site confirmed for final inspection looking to approval of the abandonment.

