Form 9-331 (May 1963)	DEPAR		INTER	SUBMIT IN TRIPLI (Other instructions verse side)	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.					NM-0140435 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1.	Use "APPL	posats to drill or to deer ICATION EOR PERMIT-	pen or plus —" for such	y back to a different reservoir. proposals.)	7. UNIT AGREEMENT NAME
WHILL Z GAS WELL OTHER					-
2. NAME OF OPERATOR					8. FARM OR LEASE NAME
Charles B. Read 3. ADDRESS OF OPERATOR					Lewis-Federal
P.O. Box 2126, Roswell, New Mexico 88201					9. WELL NO.
4. LOCATION OF WELL See also space 17 At surface	. (Report location	10. FIELD AND POOL, OR WILDCAT Undesignated			
510' FS	SL & 660 '	FEL			11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
N. WOMEN NO.					19-8S-36E
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE
				 	Roosevelt New Mexic
16.	Check A	Appropriate Box To	Indicate	Nature of Notice, Report,	or Other Data
	NOTICE OF INT	ENTION TO:		Ua	BSEQUENT REPORT OF:
TEST WATER SHU	T-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZI	E	ABANDON*		shooting or acidizing (Other) Spud &	ABANDONMENT*
REPAIR WELL (Other)	i	CHANGE PLANS		(Note: Report re	esults of multiple completion on Well completion Report and Log form.
0-14-69:	Ran 369' class ''H	" cmt. Plug d	.own @	VPS csg, set @ 350 2:00 A.M. 10-14- 500 PSI for 30 min	69. Cmt circ.
					.
	·//				•
18. I hereby certify the SIGNED	hat the foregoing	m - 1.	ritle	Agent	DATE 10-15-69
(This space for F		·	ritle	AP	PROVED
CONDITIONS OF			.A.LUE:	······································	T 16 1969
				Q Q	1 (0 1000

*See Instructions on Reverse Side