

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Div. **Jun**  
**1625 N. French Dr.**  
**Hobbs, NM 88240**

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well <input type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other TA	5. Lease Designation and Serial No. <b>NM 041698A</b>
2. Name of Operator Plains Petroleum Operating Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 415 W. Wall, Suite 1000, Midland, TX 79701 (915) 683-4434	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980 FSL & 660 FEL, Sec 14 (1), T8S, R37E	8. Well Name and No. Bluitt SA Federal #9
	9. API Well No. 30-041-20250
	10. Field and Pool, or Exploratory Area Bluitt San Andres Assoc.
	11. County or Parish, State Roosevelt, NM


12. **CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 4-06-00 1) Notify BLM - JRH & Notify NMOCB- BP.  
4-10-00 2) Set pkr @ 4300', pressure test BP @ 4346 w/ 2 sx cmt. to 500 PSI.  
3) Pressure test 5-1/2" csg. to 500 PSI.  
4) Circulate hole w/ 10# MLF.  
5) Spot 80 sx cmt. 3000-2210'.  
6) Perf @ 550'.  
7) Sqz. 50 sx cmt under pkr @ 30', communication up 5-1/2 X 8-5/8" csg. Displaced TOC to 250'.  
4-11-00 8) RIH & Tag TOC @248'.  
9) Circulate 20 sx cmt. 60' to Surface.  
10) Will install dry hole marker, backfill cellars, cut deadmen. ASAP.



14. I hereby certify that the foregoing is true and correct

Signed [Signature] Title Sierra Well Service Area Manager Date 4-11-00

(This space for Federal or State office use)

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
Conditions of approval, if any:

RECEIVED

APR 24 2000

BLM  
ROSWELL, NM