

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Eugene E. Nearburg		8. FARM OR LEASE NAME Kirkpatrick Federal	
3. ADDRESS OF OPERATOR 3303 Lee Parkway, Dallas, Texas 75219		9. WELL NO. 7	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL and 660' FEL		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4016.4 GR	
		11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA Sec 14, T8S, R37E	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	Temporary Abandon		<input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Remove wellhead and pull tubing.

Place swage and valve in top of 5 $\frac{1}{2}$ " casing.

Temporarily abandon until needed as injection well. The hole is cased to 4788'. PBD - 4605'.

I hereby certify that the foregoing is true and correct

ED James B. Blackman

TITLE Petroleum Engineer

DATE 5-13-70

space for Federal or State office use)

APPROVED BY
SIGNATURES OF APPROVAL, IF ANY:

TITLE

APPROVED

MAY 19 1970

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

RECEIVED

MAY 1 1970

OIL CONSERVATION COMM.
HOUSTON, TEX.