

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Dry Hole		5. LEASE DESIGNATION AND SERIAL NO. HM-045570	
2. NAME OF OPERATOR Skelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME --	
3. ADDRESS OF OPERATOR P. O. Box 1351, Midland, Texas 79701		7. UNIT AGREEMENT NAME --	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL and 1980' AAL Sec. 15-28-38E		8. FARM OR LEASE NAME Mexico "V" Federal	
14. PERMIT NO. --		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) UNKNOWN		10. FIELD AND POOL, OR WILDCAT Undesignated Blufft San Andres Associated	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15-28-38E	
		12. COUNTY OR PARISH Roosevelt	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	☐	PULL OR ALTER CASING	☐
FRACTURE TREAT	☐	MULTIPLE COMPLETE	☐
SHOOT OR ACIDIZE	☐	ABANDON*	☒
REPAIR WELL	☐	CHANGE PLANS	☐
(Other)	☐		☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	☐	REPAIRING WELL	☐
FRACTURE TREATMENT	☐	ALTERING CASING	☐
SHOOTING OR ACIDIZING	☐	ABANDONMENT*	☐
(Other)	☐		☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

The following work has been done:

1. Drilled to total depth of 4940'.
2. Tested San Andres formation with no commercial quantities of oil or gas present in any zone.

We propose to plug and abandon as follows:

1. Run tubing and spot cement as follows:

40 sacks cement 4500' - 4600'

40 sacks cement 2300' - 2400'

40 sacks cement at base of 8-5/8" OD casing at 192' (20 sacks inside and 20 sacks outside casing shoe).

10 sacks 10' to surface.

All intervals not cemented will be filled with 10# drilling mud.

2. Set dry hole marker.

Verbal approval given to H. O. Woods by Arthur R. Brown 7/27/70.

18. I hereby certify that the foregoing is true and correct


SIGNED Arthur R. Brown TITLE Dist. Adm. Coordinator DATE July 27, 1970

(This space for Federal or State office use)

APPROVED BY Arthur R. Brown TITLE DISTRICT ENGINEER DATE JUL 28 1970

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.