Form 9-331 (May 1963)	UNITED STATES SUBMIT IN TRIPLE DEPARTMEN. OF THE INTERIOR Verse side) GEOLOGICAL SURVEY	Te Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM-6871
(Do not a	SUNDRY NOTICES AND REPORTS ON WELLS use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR THIBE NAME
1. OIL (XT)	GAS	7. UNIT AGREEMENT NAME
2. NAME OF OPER	c C. Hanks	8. FARM OR LEASE NAME Fran Federal 9. WELL NO.
	Hobbs Pipe & Supply, Box 2010, Hobbs, N. M.	1
4. LOCATION OF V See also space At surface	WELL (Report location clearly and in accordance with any State requirements.* re 17 below.)	10. FIELD AND POOL, OR WILDCAT
	Unit H, 1980' FNL & 660' FEL	SURVEY OR AREA 33 35 25 - 85 - 36 E
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISE 13. STATE ROOSEVELT N. M.
16.	Check Appropriate Box To Indicate Nature of Notice, Report,	
	NOTICE OF INTENTION TO: 8	UBSEQUENT REPORT OF:
TEST WATER	R SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL
FRACTURE TR		G ABANDONMENT [•] X
REPAIR WELL		
(Other)	(NOTE: Report) Completion or R	ecompletion Report and Log form.)
l. Ra	prosed on COMPLETED OFERATIONS (Clearly state all pertinent details, and give pertinent work. If well is directionally drilled, give subsurface locations and measured and true s work.) An CIBR 93600 with 35' cement on top. Daded hole w/mud-laden fluids.	
	potted a 35 sx plug $@$ stub of 5-1/2" casing	, 4,745'.
4. Sp	potted a 50 sx plug in & out of stub of $8-5$,	/8" casing, 1,250'.
5. Sp	potted a 60 sx plug in & out of base of sur:	face casing, set @ 440'.
6. Sp	potted a 10 sx top hole plug & erected a 4"	regulation marker.
7. We	ell was plugged and abandoned on $3/15/74.'$	
18. I hereby certi	tify that the foregoing is true and correct	
signed	<u>A Agent</u> TITLE Agent	DATE 4/24/74
(This space f	for Federal or State office use)	JV - Jr
APPROVED : CONDITIONS	S OF APPROVAL, IF ANY:	0 1974 - AND
	*See Instructions on Reverse Side SEP	R. BRUNEER

,