

COPY TO O.E.G.

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR

American Petrofina Co. of TX

3. ADDRESS OF OPERATOR

Box 1311, Big Spring, TX 79720

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FWL, 660 FSL, Sec. 20, T-8-S  
AT TOP PROD. INTERVAL: R-36-E  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☒  
(other) ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

SEP 18 1980

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10-20-80

1. Move in casing pulling unit.
2. Set cast iron bridge plug in 5-1/2" casing @ 9650' and dump 50' cement on top.
3. Set cast iron bridge plug in 5-1/2" casing @ 8390' and dump 50' cement on top.
4. Cut 5-1/2" casing at 5000' and pull casing.
5. Spot 50' cement in and out of 5-1/2" casing stub, using mud laden fluid to spot.
6. Spot 50' cement in and out of 8-5/8" casing shoe at 4087'.
7. Spot 50' cement in and out of 13-1/2" casing shoe at 411'.
8. Set 10 sk cement plug at surface and place 4" pipe marker.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED J. C. Chapman TITLE Asst. Dist. Mgr. of Prod. DATE September 9, 1980

(Orig. Sgd.) GEORGE H. STEWART (This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

DATE SEP 18 1980  
TITLE DISTRICT ENGINEER

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant above plugs; amount, size, method of parting of any casing, liner or tubing pulled; and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPO : 1975 O - 214-149

SEP 20 1980

CONSERVATION DIV.