Form 9-331 (May 1963)

UNIDED STATES DEPARTMEN' F THE INTERIOR (Other instructions (other instructions (other instructions))

Form approved. O. C. O. Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

:	имо497735				
the not use this form for	NOTICES AND REPORTS (proposals to drill or to deepen or plug b PPLICATION FOR PERMIT—" for such po	ack to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
1.	7. UNIT AGREEMENT NAME				
WELL X GAS OT	-1'				
2. NAME OF OPERATOR	8. FARM OR LEASE NAME NCT-1				
TEXACO Inc.	M.A. Cunningham Federal				
3. ADDRESS OF OPERATOR	9. WELL NO.				
P.O. Box 728 - Hob	1				
4. COUNTION OF WELL (Report loc	10. FIELD AND POOL, OR WILDCAT				
See also space 17 below.) At surface	Brave (Wolfcamp) Undesig-				
1980' FNL and 660' FWL Section 26, T-7-S, R-35-E			11. SEC., T., E., M., OE BLK. AND nated		
·			Sec. 26, T-7-S, R-35-E		
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE		
Regular	4186' GR	Roosevelt New Mexico			
16. Che	ck Appropriate Box To Indicate N	lature of Notice, Report, or (Other Data		
•• •			QUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL		
PRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING		
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	X ABANDONMENT*		
REPAIR WELL	CHANGE PLANS	(Other)	a of multiple completion on Well		
(Other)	ii	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			
17. DESCRIBE PROPOSED OR COMPLE proposed work. If well is nent to this work.)*	TED OPERATIONS (Clearly state all pertinent directionally drilled, give subsurface local	at details, and give pertinent dates tions and measured and true vertices.	s, including estimated date of starting any cal depths for all markers and zones perti-		
	Total Dept	h 7625 '			
	Plug Back Total				
	5-1/2" OD 14, 15.5 and 1		t 7625 '		
)-1/2 0D 1., 2/1/ mid 2	.,			

Perforated 5-1/2" OD casing w/2 JSPF @ 7580', 7584', 7587' - 7589', 7592' - 7598' and 7601' - 7605'. Job complete 2:00 PM, January 16, 1971. Ran tubing w/packer and set packer at 7500'.

Acidized perforations 7580' - 7605' w/1000 gals 15% HEA. Job complete 9:45 PM, January 16, 1971.

18. I hereby certify that the foregoing is true and correct SIGNED	Assist TITLE Superi	ant District ntendent		
This space for Federal or State office use) APPROVED BY	TITLE	ACCEPTED FO	R RECORD 1971	
* \$	ee Instructions on I	U. S. GEOLOGI Reverse Side 0335, NE	CAL SURVEY W MEXICO	