

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFF CE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG-4982	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>BTA Oil Producers</u>		8. Farm or Lease Name <u>Pruitt 7103 JV-D</u>
3. Address of Operator <u>104 South Pecos, Midland, Texas 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>"P"</u> <u>554</u> FEET FROM THE <u>South</u> LINE AND <u>554</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>8-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat <u>Vada-Penn</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>4289 GL, 4300 KB</u>		12. County <u>Roosevelt</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Completed Plugging as Follows:

Cut & pulled 8-5/8" csg @ 1286'
25 sx @ 1286' (8-5/8" stub)
25 sx @ 365' (12-3/4" shoe)
10 sx @ surface
Installed dry hole marker per NMOCC Regulations
Plugged & Abandoned 11-12-71

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED L. A. Boyce TITLE Production Clerk DATE 11/22/71

APPROVED BY [Signature] TITLE Director DATE 11/22/71

CONDITIONS OF APPROVAL, IF ANY: