

Murphy Hinton #1

5/5/2000

A 22 8 37

Possible csg collapse & loss of salt
+bg out @ 2896 ft

Run + set cmt, ret to 2850 ft

Squeeze 50 sx under ret

Sting out of Ret

Spot 50 sx cmt 2850 - 2350

Ptg

Per f 5 1/2 csg @ 415'

50' under 8 5/8 shoe @ 365'

Break circ between 5 1/2 x 8 5/8

Circ cmt to surf

Leave 100' cmt in 5 1/2 above
ports

woc.

Tag Plug

10 sx @ surf

If unable to
Ptg

Johnny Gabaldon
748 4583

BEF
Bert
Hinton