

OPERATOR: Union Oil Company of California  
LEASE: Tucker  
WELL NO: 2  
LOCATION: Section 4, Unit Letter K,  
Township 7 South, Range 33 East  
Roosevelt County, New Mexico

DRILL STEM TESTS

- November 10, 1976 - Ran Drill Stem Test No. 1, Canyon Sand, from 8,836' to 8,865'. Initial 15 minute pre-flow with weak blow, shut in 1 hour. Tool open 1 hour with very weak blow, decreasing to no blow after 25 minutes. IHP 4891, IFP 367, ISIP 2630, FFP 412 to 956, FSIP 2317, FHP 4715, bottom hole temperature 160 degrees.
- November 15, 1976 - Ran Drill Stem Test No. 2, Strawn zone, from 9,115' to 9,185'. Attempted to set packers- and packers failed.
- November 16, 1976 - Ran Drill Stem Test No. 3, Strawn zone, from 9,068' to 9,185'. Initial 30 minute pre-flow with weak blow, increased to fair blow. Shut in 1 hour. Reopened tool for 1 hour with fair blow. Recovered 600' of drilling mud, with no show of oil, gas or water. IHP 4872 to 4891, IFP 321, FFP 237 to 504, FSIP 3191 to 3299, FHP 4740, bottom hole temperature 136 degrees.

RECEIVED

FEB 6 1976

OIL CONSERVATION COMM.  
HOBBS, N. M.