

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-2980	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFRACK OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" FORM C-101 FOR SUCH PROPOSALS.)</small>		
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry</u>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
<u>Flag-Redfern Oil Company</u>		<u>Hanks-State</u>
3. Address of Operator		9. Well No.
<u>P.O. Box 23 Midland, TX 79702</u>		<u>1</u>
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>0</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>16</u> TOWNSHIP <u>8-S</u> RANGE <u>34-E</u> N.M.P.M.		<u>Undesignated</u>
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<u>4287 GL</u>		<u>Roosevelt</u>

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
9-21-78

Displaced hole with 10# mud.
Spotted 25 sx. cement at 4564.
Tagged top of cement at 4280.
Spotted 25 sx. cement at 2253.
Cut off casing.
Spotted 10 sx. cement and installed dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <u>[Signature]</u>	TITLE <u>Petroleum Engineer</u>	DATE <u>10-2-78</u>	
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 2 1979</u>	
CONDITIONS OF APPROVAL, IF ANY:			