

Production Casing: 6

---

---

---

---

---

D. Wellhead Equipment:

Larkin Bradenhead

Larkin Tubinghead

---

VI. Mud Program:

A. Surface Hole:

Fresh water gel with sufficient viscosity to make hole

---

---

---

---

---

---

---

---

---

---

---

B. Production Hole:

Allow mud to become salt saturated; add starch and brine gel to  
lower water loss to 15 cc and viscosity to 40 cp

---

---

RECEIVED

JUN 19 1979

SEL. COMMISSION COMM.  
HON. S. M. R.