

Sundry Notice
Plug & Abandon
Page 2

Flag-Redfern Oil Company
Westall Federal No. 1
Tomahawk (San Andres)
Roosevelt County, NM

6. Spot 25 class "C" cement plug at surface.
7. Cut casing off below ground level, weld plate on and permanently mark well with a 4" pipe extending 4' above ground level with the following information:

Flag-Redfern Oil Company
Westall Federal No. 1
SW/4 NW/4 Sec. 29, T-7-S, R-32-E

8. Clean up location

Note: Cement plugs to be spotted using 2 3/8" tubing.
Please refer to attached wellbore diagram for additional details.