DISTRIBUTION				Supersede	Form C-103 Supersedes Old C-102 and C-103	
SANTA FE	NEW MEXICO	OIL CONSI	ERVATION COMMISSION	Effective	1-1-65	
FILE	4		,	Sa. Indicate	Type of Lease	
9.s.G.\$.	4			State	Fee X	
LAND OFFICE				5. State Oil	Cas Lease No.	
PERATOR	J					
C1.101	DV NOTICES AND DE	DODTE ON	WELLS		THITTITITI	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT THE THE FORM FOR PROPORTED TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. 100 NOT THE THE FORM FOR PERMIT AT JOHN C-1011 FOR SUCH PROPOSALS.						
, T MAPPOICA	Aldd LON MERWIT To Thomas C	- I (III FEN 35C	- PROPOSACS.	7. Unit Agree	ement Name	
Site X GAS WELL X	OTHER-			8, Farm or L	ease Name	
				DAD	TON	
EL RAN, INC.				9. Well No.	101	
P. O. BOX 911 LUBBOCK, TEXAS 79408				ļ	1	
Location of Well				10. Field an	10. Field and Pool, or Wildcat	
	2200	North	LINE AND FE	CHAV	EROO	
UNIT LETTER G	2200 FEET FROM THE	MOLEIL	CINE AND		rillillilli.	
East	34	7-S	RANGE 32-E	IIIII waxa		
THE LINE, SECT	ICN YOWNS	HIP	XANGE			
THITTINITY:	15. Elevation (Show whether	DF, RT, GR, etc.)	12) County		
	(11111)	4474 GR		100-1211	<u>est 111111111111111111111111111111111111</u>	
Check	Appropriate Box To	Indicate N	ature of Notice, Report	or Other Data		
	INTENTION TO:			QUENT REPORT	OF:	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,,,,,					
PERFORM REMEDIAL WORK	PLUG AND	ABANDON []	REMEDIAL WORK	A	LTERING CASING	
TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.		LUS AND ABANDONMENT	
LL OR AUTER CASING	CHANGE PI	LANS	CASING TEST AND CEMENT JOB			
			ОТНЕЯ			
OTHER	<u> </u>					
. Tescrice in posed or Completed (1	ails and ains partinum dates	including estimated dat	e of starting any proposed	
(i) Describe in providing Completed (work) SEE RULE 1103.	Operations (Clearly state at	i penineni aei	aits, and give pertinent dates, i	including commercial	2 ., 0,,,	
El Ran, Inc following proced		andoned t	the above reference	d well using t	he	
	1. Set	CBP 4100)' with 100' plug a	hove BP		
2. Shot 4½ off and loaded hole with 9½# mud with 100'						
	cement plug - from 2100 to 2285 tagged plug					
	3. Set	100' cer	ment plug from 1735	' to 1635' tag	nlug	
			g with marker at su		r	
•	5. Location is ready for inspection at this time.					
			•			
		•				
	ion above is true and comple	ete to the best	of my knowledge and belief.			
<i>A</i>						
11/67 / 0	.7	V-	lce-President	DATE	/28/84	
William WW Admela	<i>/</i> ?	11744				
716.	10.	<u>.</u> C	IL & GAS INSPE	CTOR	MAR 2 7 1985	