

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator El Ran, Inc.</p> <p>3. Address of Operator P. O. Box 911, Lubbock, Texas 79408</p> <p>4. Location of Well UNIT LETTER <u>H</u> <u>2200</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>7-S</u> RANGE <u>32-E</u> NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Bergstrom</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Chaveroo SA</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 4486 KB</p>		<p>12. County Roosevelt</p>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

El Ran, Inc. proposes to Plug and Abandon the above referenced well using the following procedure: Perfs 4142 - 4294

1. Set CBP 4100' with 100' plug above BP
2. Shoot 4 1/2" off and load hole with 10# mud with 100' cement plug.
3. Set 100' cement plug from 1750 to 1650'.
4. Set 10' plug with marker at surface.

Tag plug

Tag plug

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Robert R. Ranch</u>	TITLE <u>Vice-President</u>	DATE <u>Sept. 8, 1982</u>
APPROVED BY <u>Eddie W. Seay</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>SEP 10 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

**SEP 9 1982**

**O.C.D.  
HOBBS OFFICE**