Form 9–331 Dec. 1973 P. O. BOX 1980	MMISSION Form Approved. Budget Bureau No. 42_R1424		
UNITED STATES HOBBS, NEW MEX	CO- 85240 NM	18846	0 % d
GEOLOGICAL SURVEY	6. IF INDIAN, AL	LOTTEE OR TRIB	ENAME
		-1.50 S	<u>်ကိုသာ</u> ငွေလီ <u>ဘ</u>
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEN	MENT NAME	st, alia capio
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEA	SENAME	S A S
1. oil 版 gas well other	9. WELL NO.	<u>\$.50                                    </u>	
2. NAME OF OPERATOR	3: WELL 110	파일 () 독급왕   첫	1639 1639
EL RAN, INC.	10. FIELD OR WIL	DCAT NAME	13 P
3. ADDRESS OF OPERATOR	CHAVEROO		3 - 7 7
P. O. BOX 911 LUBBOCK, TEXAS 79408	11. SEC., T., R., A	1., OR BLK. AND	SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)		T-78, R32E	5 7 5 5 9 5 5 9 5
AT SURFACE: Unit Letter L, 1650 FSL & 990 FWL	12. COUNTY OR		
AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: 4262KR	Roosevelt		w Mexico
AT TOTAL DEPTH: 4262KB  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.		# 6 C
REPORT, OR OTHER DATA	15. ELEVATIONS	<u>. 3 . 9 . 5</u>	<u>네고</u> 문
DECUEST FOR ADDROVAL TO:		GR GR	a; AIYU WU) 옵투급
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			4 t 9
FRACTURE TREAT	. 4.		36 To 16 To
SHOOT OR ACIDIZE			
REPAIR WELL	(NOTE: Report resu	Form -330	pletton or zone
MULTIPLE COMPLETE	change on	7 On # 9-33035	<b>建</b> 2000 是
CHANGE ZONES   ABANDON*  CT		Star g	
ABANDON* LJ XX (other)			<b>9</b> 日本
	<u> </u>		
<ol> <li>DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen</li> </ol>	all pertinent detail ectionally drilled, g to this work.)*	s, and give part ive subsurface ic	inent dates, cations and
Set CIBP at 4159' and spot 100' plug on	top		
Shot CSG off at 1698' and pulled same	# 1. -	Maria ga	हें जिल्हा जिल्हा जिल्हा
Loaded hole with 9½# mud and spotted 10	' plug		တွင်းနှင့် ပိန်းစ
from 2150' to 1950' tag plug. Loaded hole with 9½# mud			
Spot 100' plug from 1762' to 1662', 100	ded remainde:	r of hole w	ith
9½# mud and placed 10' surface	lug.		7 U V
Set marker and back ripped location and	road.		7
Location is ready for final inspection	at this time	şerî x ê	
	ين ا		요작. 교향구
			OF T
Cubayyfaca Cafaby Valyar Many, and Type			등 (현실 전 분 경 전 분 경
Subsurface Safety Valve: Manu. and Type		Set @	<u> </u>
18. I hereby certify that the foregoing is true and correct	जें हैं। इं		4 0 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
SIGNED WWW Kande In TITLE Vice-Presider	t DATE Sept	ember 28.	1984
APPROVED (This space for Federal or State office	use)		5 2 W
APPROVED APPROVED BY PETER W. CHESTER TITLE	DATE	0 1 0 T	A S
CONDITIONS OF APPROVAL, IF ANY:	77.	3 7 3 7 N	¥ 3 #

APR 2 5 1986.

BUREAU OF LAND MANAGEMENT Instructions on Reverse Side ROSWELL RESOURCE AREA

NPR 29 66