m Approved. Budget Bureau No. 42-R1424

UNITED STATES						
DEPARTMENT	OF	THE	INTERIOR			
GEOLOGI	CAL	SUR	VEY			

NM-15019		M. M	<u>्</u> रिक्ष १८५५ १८५
6. IF INDIAN	ALLOTTEE (	OR TRIE	BE NAME
7. UNIT AGR	EEMENT NA	ME	
8. FARM OR			
Cone Feder	al		
9. WELL NO.			
25	6.3		
10. FIELD OR	WILDCAT NA	ME	: "
Tomahawk,	San Andr	es	
11. SEC., T., F	., M., OR BL	K. AND	SURVEY OR
AREA		ķ .	
NE SW Sect	ion 27,	T.7S.	, R.32E.
12. COUNTY C	R PARISH	13. ST	ATE
Roosevelt		New	Mexico
14. API NO.	,		<u>.</u> .
	<u> </u>		

CLOCOGOTE CONTE	S. II INDIVITY NEED THE ON TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
1. oil gas other DRY	Cone Federal	
2. NAME OF OPERATOR	9. WELL NO. 25	
SUNDANCE OIL COMPANY	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR #910, 1776 Lincoln St., Denver, CO 80203	Tomahawk, San Andres	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
below.)	NE SW Section 27, T.7S., R.32E.	
AT SURFACE: 1980' FSL, 1980' FWL, Unit K AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Same	Roosevelt New Mexico	• -
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.	in the
REPORT, OR OTHER DATA	15 ELEVATIONS (CHOW DE VOD AND WE	
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 4467'GL, 4479' KB	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7107 SE3 7175 KD	5 S3 - S
TEST WATER SHUT-OFF		2000,200,200
SHOOT OR ACIDIZE	RECEIVE	5
REPAIR WELL	(NOTE: Report results of multiple completion or zone	U
PULL OR ALTER CASING	change on Form 9-330.)	
CHANGE ZONES	FEB 23 1981	
ABANDON*	U.S. GEOLOGICAL SU	DI/EL
(other)	HOBBS, NEW MEXI	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state	all pertinent details, and give pertinent dates	
including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinen	rectionally drilled, give subsurface locations and to this work.)*	1.5
Received permission to P & A. Set cement plu	gs as follows:	
40 sx @ 4190'		
40 SX @ 4190 40 SX @ 2287'		
40 sx from 1922'-1822'		
10 sx surface.		
PD & rig released at 12 midnight, 2/5/81. Dr		
	y hole marker on well. WO pits	
to dry before backfilling and leveling locati		
to dry before backfilling and leveling locati	y hole marker on well. WO pits on.	
to dry before backfilling and leveling locati	y hole marker on well. WO pits on.	
to dry before backfilling and leveling locati	y hole marker on well. WO pits on.	
Subsurface Safety Valve: Manu. and Type		
Subsurface Safety Valve: Manu. and Type	on。 Set @Ft.	
Subsurface Safety Valve: Manu. and Type	on。 Set @Ft.	
Subsurface Safety Valve: Manu. and Type  18. I herety certify that the foregoing is trule and correct  SIGNED Notan L. Ashburn President	on.  Set @ Ft.  DATEFebruary 19, 1981	
Subsurface Safety Valve: Manu. and Type  18. I hereby certify that the foregoing is true and correct  SIGNED Notan L. Ashburn TITLE President  Ashburn This space for Federal or State office	On.  Set @Ft.  DATE _February 19, 1981	
Subsurface Safety Valve: Manu. and Type  18. I herety certify that the foregoing is trule and correct  SIGNED Notan L. Ashburn President	On.  Set @Ft.  DATE _February 19, 1981	

NOV 7 1984

RECEIVED

NOV -9 1984

O.C.D. HOBBS OFFICE