

TOM L. INGRAM

100 SOUTH KENTUCKY AVENUE
ROSWELL, NEW MEXICO 88201

February 11, 1982

State of New Mexico
Energy and Minerals Department
Oil Conservation Division
P. O. Box 2088
Santa Fe, NM 87501

Re: Order No. 5353
Rule No. 2

Gentlemen:

The Tom L. Ingram No. 2-Y Federal "N" was drilled and completed as a small San Andres oil producer at a location 846' FSL and 710' FEL of Section 23, T-8-S, R-37-E in Roosevelt County, New Mexico. Rule No. 2 of the above captioned order specifies within 150' of the center of the quarter-quarter section. The subject location is 186'. This location was a twin to the junked hole located 846' FSL and 660' FEL (old location plat indicated 660' FSL & 660' FEL). Upon having the new hole surveyed, it was learned that the original description of the old hole was in error. Sand dunes on the south would have prevented using the standard location.

For these reasons, it is requested that administrative approval be granted this non-standard location.

Not to cloud the picture, but the Order applied to P_2 production and this well produces from P_1 . The produced waters from each are different.

Very truly yours,



TOM L. INGRAM

TLI/mkh

cc: Energy & Minerals Dept.
P. O. Box 1980
Hobbs, NM 88240