

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐
well well other Dry Hole

2. NAME OF OPERATOR
Bliss Petroleum, Inc.

3. ADDRESS OF OPERATOR
Box 1817, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660' FW & FNL of Sec. 31

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☒

5. LEASE

NM 15332

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

~~28~~ Federal 7B

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Undesignated

11. SEC., T., R., M., OR BLK. AND SURVEY CR AREA

Sec. 31, T8S, R38E

12. COUNTY OR PARISH 13. STATE


Roosevelt

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3995' RKB



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set 5 1/2" CIBP at 8507'. Spotted 35' Cmt. on top of BP.
2. Cut 5 1/2" Csg. at 7340'. Pulled & Laid down. 170 jts. Csg.
3. Ran 2 3/8" tbg. & spotted 35 sx. cmt. plug at 7390'. Tagged TOC at 7268'.
4. Spotted thru tbg. 35 sx. cmt. plug at 5475' - 5355'.
5. Spotted thru tbg. 60 sx. cmt. plug at 4247'. Tagged top of cmt. inside 8 5/8" at 4140'.
6. Spotted thru tbg. 35 sx. cmt. plug inside 8 5/8" at 2100' - 1978'.
7. Spotted thru tbg. 15 sx. cmt. plug inside 8 5/8" from 50' to surface.
8. Cut off well head. Installed dry hole marker. Work completed 6-23-82.

Subsurface Safety Valve: Manu. and Type

Set @ Fl.

18. I hereby certify that the foregoing is true and correct

SIGNED

Paul Bliss

TITLE President

DATE 6-29-82

APPROVED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

NOV 4 1982

FOR

JAMES A. GILLHAM

DISTRICT SUPERVISOR See Instructions on Reverse Side