

UNITED STATES P. O. BOX 1830
ROSWELL, NEW MEXICO
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR
H. L. Brown, Jr.

3. ADDRESS OF OPERATOR
P. O. Box 2237, Midland, Texas 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit 0, 330' FSL, 2310' FEL
AT TOP PROD. INTERVAL: 330' FSL, 2310' FEL
AT TOTAL DEPTH: 330' FSL, 2310' FEL

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) <u>Production String</u>		

5. LEASE
NT 17450

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal K

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Bluitt (Wolfcamp)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34, T7S, R37E

12. COUNTY OR PARISH
Roosevelt

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
4058.3

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-27-82

Set production string of 5 1/2" casing. Ran 197 jts of 17# & 15.50# (8174.26') set @ 8165'. Cement w/175 sx Class H + 700 sx 50/50 2 Class H. Good circulation throughout job. Plug down @ 5:15 p.m. 7-28-82. Release rig @ 11 p.m. 7-28-82.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Jean Mills TITLE Production Clerk DATE October 13, 1982

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD (ORIG. SGD.) DAVID N. GLASS

OCT 19 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED

OCT 18 1982

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

RECEIVED

OCT 22 1982

G.C.D.
HOBBS OFFICE