## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

(0-128 -4111468	T	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.	1	
LAND OFFICE		
OPERATOR	7	

## OL CONSERVATION DIVISION

Form C-103

SANTA FE	-	SANTA FE, NEW MEXICO 87501					Revised 10-1-78		
FILE		3	ANIA FE,	IN E. W	MEXICO 87501	[	. Indicate Type		<del></del>
U.\$.G.\$.						.   34	State State		. [X]
LAND OFFICE						5.	State Oil & Ga		• 🗀
OPERATOR		)			•	-		<b>2</b>	
	SUNDR	Y NOTICES A	NO REPORT	S ON	WELLS	/		777777	THI.
(DO HOT USE TH	IS FORM FOR PRO	POSALS TO DRILL O	OR TO DELPIE OF	PING B	ICA TO A DIFFERENT RESERVAIR			////////	
1.						7.	Unit Agreemen	t Nane	
werr X	weel	OTHER-							
∠, Name of Operator						8.	8. Farm or Lease Name		
Wallace Oi	il & Gas,	Inc.					Tucke	<u>r</u>	
Address of Cherotor	laca Suit	a 950 Oi-1-	. Cit 01	, 7.	0110	9.	Well No.		
	race, suit	e 850, Okla	. CILY, O		0110		Field and Pa	ol c: Alldcat	
4. Location of Well  UNIT CETTER K . 1980 FEET FROM THE South LINE AND 1980 FEET FROM							10. Field and Fool, or Wildcet Wildcat		
UNIT CETTER K	,,	980 FEET P	ROM THESOI	ith	LINE AND PEE	ET FROM	TTTTTT	mm	m
Uoat		5		70	2.25				
THE WEST	LINE, SECTIO		TOWNSHIP	75	RANGE 33E	_ HMPM.		((((((	
THITTINE:	TITTITI	15. El	evation (Show w	hether l	OF, RT, GR, etc.)	12	. County	11111	777
		Gr.	4409'. KI	3 443	30	R	oosevelt		
16.	Check /				ature of Notice, Report				
NO		TENTION TO		1	-		EPORT OF:		
PERFORM REMEDIAL WORL	. 🔲	P	LUG AND ABANDON	· 🗀	REMEDIAL WORK		ALTER	ING CASING	
TEMPORARILY ABANDON					COMMENCE DRILLING OPHS.	_	PLUG A	ND ABANDOHME	INT .
PULL OR ALTER CABING		c	HANGE PLANS		CASING TEST AND CEMENT JOB	<u>X</u> ]			
•				$r \rightarrow 1$	OTHER			<del></del>	
OTHER				- L					
		erations (Clearly	state all pertine	nt deta	ils, and give pertinent dates, in	cluding esti	mated date of	starting any pr	roposed
work) SEE HULE 11	103.								
1-6-84 7:00 p.m. Spudded with 17 1/2" bit.									
	Commene	d drilling	operations	•					
1-8-84	Desillad	*- /OO!	g -		/ FO# TEE :				
1 0 04	Cemented	lo 400   with 400	ser 13 3/0	r, )	4.50#, J55 casing at	t 398'.		1 . 1	
	150 sxs	cement to	surface	Rimp	% CACL 2. Displaced ed plug at 700#, hel	u with t	vater, cli	rold On cciniated	3
			Juliuce.	Бамр	ed plug at 100%, he.	id for .	, min., 1	ielu OK.	
	WOC 18 h	ırs.							
8. I hereby certally that	the information	above is true and	complete to the	best of	my knowledge and belief.				
, /	/ / i	Si +h	9 2	_					
HENED 1 ACKET	a 1	Well W	TITLE	P	roduction Sec.		DATEJar	n. 11, 19	<del>)</del> 84
TAIAA	NAT CICARD	BY EDDIE SEAY							
	. & GAS	INSPECTO	$\cap \mathbf{R}$				DATE JA	N 1 6 19	J84
PPROVED BY			CAPITAL ALLES						<del></del>