Form 3160-5 (JUNE 1990)	DEPARTMEI	تات STATES NT OF THE INTERIOR LAND MANAGEMENT	N.M. Oil 1625 N. F Hobbs, NI	ONS. Division ench DPRM APPROVED Briggt Bureau No. 1004-0135 8824 Bureau No. 1004-0135 8824 Bureau No. 1004-0135
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals			LS ent reservoir.	<ol> <li>Lease Designation and Serial No. NM-36486</li> <li>If Indian, Allottee or Tribe Name</li> </ol>
SUBMIT IN TRIPLICATE				
1. Type of Well Oil Gas				7. If Unit or CA, Agreement Designation
				8. Well Name and No.
2. Name of Operator STRATA PRODUCTION COMPANY				Gallina Federal #2
3. Address and Telephone No. P. O. Box 1030				9. API Well No.
Roswell, New Mexico 88202-1030 505-622-1127			5-622-1127	30-041-20714 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Tomahawk San Andres
660' FSL & 1900' FWL				11. County or Parish, State
Section 31-7S-32E				Roosevelt County, New Mexico
12. CHECK APP	ROPRIATE BO	X(s) TO INDICATE NATURE	OF NOTICE	REPORT OR OTHER DATA
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION				
Notice of Intent		X Abandonment		
		Recompletion		Change of Plans
X Subsequer	nt Report	Plugging Back		New Construction
		Casing Repair		Non-Routine Fracturing
Final Abandonment Notice		Altering Casing		Water Shut-Off
		OTHER		Conversion to Injection
				(Note: Report results of multiple completion on Well
<ol> <li>Describe Proposed or C directionally drilled, give</li> </ol>	ompleted Operations (Cle ve subsurface locations and	arly state all pertinent details, and give pertinen measured and true vertical depths for all marke	t dates, including estimat ers and zones pertinent to	Completion or Recompletion Report and Log form.) ed date of starting any proposed work. If well is this work.)*
02/22/01:	Set CIBP at 4050'. Capped with 25 sacks cement to 3700'.			
02/23/01:	Spot 25 sacks cement at 2585'-2532. Tagged. Cut and pulled 2532' of 4 1/2" casing.			
02/26/01:	Spot 15 sacks cement at 2532'-2480'. Spot 25 sacks cement at 2225'-2125'. Spot 60 sacks cement at 1775'-1666'. Tagged.			
02/27/01	Shot 10 sacks compart at 60' Surface. Circulated 40th much			

10 sacks cement at 60'-Surface. Circulated 10# mud.

Installed Dry Hole Marker. Well is Plugged and Abandoned.

surfuce restoration is completed. 14. I hereby certify that the foregoing is true and correct Title Production Records Manager Date Signed 03/08/01 his space for Federal or State office use) pproved by (ORIG. SGD.) ALEXIS C. SWOBODA Title MAR 1 3 2001 PETROLEUM ENGINEER Date ditions of approval, if any File 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent stater representations as to any matter within its jurisdiction. \* See Instruction on Reverse Side

5CB

Approved as to plugging of the well bors Clability under bond is retained until

