Form 3160-5 November 1983) Formerly 9-331)	DEPARTM	INI D STA ENI OF TH	E INTERIOR	SUBMIT IN TRIPL: (Other instructions verse-adde)	E.	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO. NM 36489	
			epen or plug back t	WELLS to a different reservoir.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
1. OIL GAS WELL WELL	OTHER			میں بیاد ہوتا ہے۔ ایک ایک ایک ایک ایک ایک ایک ایک ایک ایک		7. UNIT AGBREMENT NAME	
2. NAME OF OPERATOR			, , , , , , , , , , , , , , , , , , ,			8. FARM OR LEASE NAME	
Yates Petroleum Corporation						Bluestem ZL Federal	
3. ADDRESS OF OPERATOR						9. WHLL NO.	
207 Sout	207 South 4th St., Artesia, NM 88210						
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)						10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface					12	Undes. Bluitt San Andres	
1650	FNL & 231() FEL, Sec.	20-T8S-R38E			11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
				North A		Unit G, Sec. 20-T8S-R38E	
14. PERMIT NO.		15. ELEVATIONS (S)	how whether DF, RT, G	iR, etc.)	[·	12. COUNTY OR PARISH 13. STATE	
		39	76'_GR		1	Roosevelt NM	
16.	Check App	propriate Box To	Indicate Natur	e of Notice, Report, o	r O	ther Data	
N	OTICE OF INTENT	10N TO :	1	80 Ba	IL Q U I	INT REPORT OF :	
TEST WATER SHUT-OF	уч <mark>г</mark>	ILL R ALTER CASIN	iG	WATER SHUT-OFF	X	REPAIRING WELL	
FRACTURE TLEAT	М	ULTIPLE COMPLETE		FRACTURE THEATMENT		ALTERING CASING	
SHOOT OF ACIDIZE	AI	BANDON*		SHOOTING OR ACIDIZING	x	ABANDONMENT	
REPAIR WELL	CI	IANGE PLANS		(OtherSurface, Pr			
(Other)				(NOTE : Report resu Completion or Reco	ults o munic	of multiple completion on Well tion Report and Log form.)	
17. DESCRIBE PROPOSED OR proposed work. If rient to this work.) •	COMPLETED OPER. well is direction	ations (Clearly sta ally drilled, give su	te all pertinent deta absurface locations a	alls, and give pertinent da and measured and true ver	tes, l tical	including estimated date of starting any depths for all markers and zones perti-	
Spudded 12-1/4"ho	ole 9:45 PM	1 5-21-84.	Ran 54 jts	of 8-5/8" 24# J-	-55	ST&C casing as follows:	
						ide shoe set at 2285'.	
Insert float set	at 2242'.	Cemented w	/675 sacks	Pacesetter Lite	and	d 3% CaCl2. Tailed in	
) psi in 12 hours. PD	
10:45 PM 5-24-84. Bumped plug to 750 psi, released pressure and float held okay. Cement							
irculated 50 sacks. WOC. Drilled out at 10:45 AM 5-25-84. WOC 12 hours. NU and tested							
o 1000 psi for 30 minutes. OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.							
TD 4940'. Ean 12	0 jts 5-1/	/2" 14# J-55	ST&C casin	g set 4940'. Re	gu]	lar guide shoe set 4940'.	
Super Seal float collar set 4910'. Cemented w/200 sacks Class C .5% CF-2, .2% AF-S, 3% KCL.							
						31-84. Bumped plug to	
000 psi for 30 minutes, released pressure, float and casing held okay. WOC 18 hrs. WIH and							

18. I hereby certify that the foregoing is true and correct		
SIGNOPT - and a hold Cett	TITLEProduction Supervisor	DATE 6-22-84
(This space for Federal or State office use)		
ACCEPTED FOR RECORD		
APPROVED BY	TITLE	DATE
JUN 27 1984		
*Sei	eAnstructions on Reverse Side	

perforated $4.765-4790\frac{1}{2}$ ' w/10 .42" holes as follows: 4765, 67, 69, 72, 74, 76, 80, 85, $87\frac{1}{2}$, 90 $\frac{1}{2}$ '. Acidized perfs $4765-4790\frac{1}{2}$ ' w/2500 gal 20% NEFE acid and 15 ball sealers. Swabbed well with trace of oil. WIH and perforated 4697-4730' w/10 .42" holes as follows: 4697, 99, 4707, 09, 14, 22, 24, 26, 28 and 30'. Acidized perfs 4697-4730' w/2000 gal NEFE acid and 15 ball

sealers. Swabbing and recovering load.

Title 15 U.S.C. Section makes makes makes for any person knowingly and willfully to make to any department or agency of the United States any false, licitious or fraudulent statements or representations as to any matter within-its jurisdiction.

