UN, 2D STATES N. M. BUBMIT IN TRIPI FET DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OBBS, NEW MEXICO 88240 Budget Bureau No. 1004-0135 Expires August 31, 1985 Form 3160-5 (November 1983) LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) NM57710 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL CAB WELL OTHER S. FARM OR LEASE NAME 2. NAME OF OPERATOR MWJ 34 Federal MWJ PRODUCING COMPANY 9. WELL NO. 3. ADDRESS OF OPERATOR #1 Midland, Texas 79701 400 W., Illinois - Suite 1100 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*
See also space 17 below.) 10. FIELD AND POOL, OR WILDCAT Vada - Penn At surface 11. SHC., T., R., M., OR BLK. AND SURVEY OR ARMA Unit BC 660' FNL & 1340' FWL Section 34 Sec 34, T-8S, R-36E 12. COUNTY OR PARISH 13. STATE 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. New Mexico Roosevelt 4102' KB API #30 041 20820 4084' GL Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data 16. RUBEROUENT REPORT OF: NOTICE OF INTENTION TO: REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT ARANDON MENT SHOOTING OR ACIDIZING ABANDON<sup>4</sup> SHOOT OR ACIDIZE CHANGE PLANS (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) \* POOH W/tbg, anchor catcher, SSN & perf sub. RU Wedge W/L, 3/27/89: MI & RU PU. ran & set CIBP @ 9700' w/35' cmt on top. Set 25 sx cmt plug from 7700-3/28/89: RIH w/tbg, RU Halliburton & pmpd 10# mud. 7600'. RU Wedge W/L & ran 5-1/2" csg cutter. 3/29/89: Cut csg @ 4236, RD Wedge W/L. Pulled & LD 102 jts 5-1/2" csg & stub. Halliburton spt'd 100 sx cmt plug @ 4236', tagged plug @ 4095'. 3/30/89: Halliburton spt'd 40 sx cmt plug from 478' to 368' & 20 sx cmt plug from 50' to surface. RD & MO. 3/31/89: Installed dry hole marker. Well P & A.

segoing is true and correct i merely certify that DATE 4/3/89 THILE Pat Drexler-Agent APPROVED (This space for Federal or State office use) PETER W. CHESTER TITLE Approved as to plugging of the well bore. APPROVED BY CONDITIONS OF APPROVAL, IF ANY: Liability under bond is retained until 1 1989 JUN surface restoration is completed, \*See Instructions on Reverse Side BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA

to any department or agency within its jurisdiction.