Form (160 = 7) (November 105), (Formerly 9=331

HNIT) STATES น และเดลโนเซ็าเพื่อให้เก็บได้

Businet Burelli No. 1.814-1

0111	JIAILS	N HENRY BEENE COMMIT	. GIA	Ext	ures August	-31 - 198	ς,
DADTMENT	OF THE INT	ERIPROSESTATES	re- i				
PARTIMENT	OF THE INT	ELLIN DY ARRAIGNED S	- 1	O. LEASE	DESIGNATION	AND SEE	1.6
		P. U. BUA 1000	1				
\mathbf{p}_{1} \mathbf{p}_{2} \mathbf{p}_{3} \mathbf{p}_{4} \mathbf{p}_{4} \mathbf{p}_{4} \mathbf{p}_{4}	_ X X I D X I X X I X C C I	AFXIT					

, - · · · · · · · · · · · · · · · · · ·	BUREAU OF LAND M	ANAGEMENT _H	O. BOX 1930 BBS, NEW MEXICO	BS240 NM 0145685	
	NDRY NOTICES AND of form for proposals to drill or to Use "APPLICATION FOR PERM	REPORTS ON	1 WELLS	6. IF INDIAN, ALLOTTRE OR TRIBE	NAME
OIL GAN WELL WELL 2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME				
FINA OIL &	Horton Federal	Horton Federal B. WELL NO. / API No.			
Box 2990, 4. Location of Well See also space 17 b At surface	38, 30-041-20821- 10. FIELD AND POOL OR WILDCAT Milnesand San And	38, 30-041-20821- 10 FIELD AND POOL OR WILDCAT Milnesand San Andres			
1700' FNL	& 920' FEL, Sec. 30,	T-8-S, R-35-	E	11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA	
14. PERMIT NO.	1	(Show whether DF, RT,		30, 8S, 35E, NMPM 12. COUNTY OR PARISH 13. STATE	
		.5 _GR_4213		Roosevelt New Me	xico
16.	Check Appropriate Box	to Indicate Nati			
	NOTICE OF INTENTION TO:	[1	ន:: BS	EQUENT REPORT OF:	7
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLE ABANDON®	!1	WATER SHUT-OFF FRACTUBE TREATMENT SHOOTING OR ACIDIZING	REPAIRING WELL ALTERING CASING ABANDONMENT®	- -
REFAIR WELL	CHANGE PLANS		(Other)	ilts of multiple completion on Well	_
(Orher) Set 5 17. DESCRIBE PROPOSED proposed work, nent to this work	OR COMPLETES OPERATIONS (Clearly If well is directionally drilled, give	state all pertinent de subsurface location		upletion Report and Log form.) tes, including estimated date of starth ticul depths for all markers and zones	ng any s perti-
11-20-87	Drilled 7-7/8" hole hole logs.	to TD of 480	0' at 1:15 a.m.,	deviation 3/4°. Ran op	en-
11-21-87	Ran 10 centralizers	on bottom 10 200 sx, Cl.	jts of casing. "H" with 6#/sk s	th $5\frac{1}{2}$ " guide shoe at 48 HOWCO cemented with 120 alt. Bumped plug 8:15 rig 9:00 a.m.)0 sx
CMT: nh					
18. I hereby certify th	at the foregoing is true and correct	<u> </u>			
	E. Smelley Enderal or State office (se)	TITLE Dist.	Mgr. of Drilling Production		
APPROVED BY _	_	TITLE		DATER W. CHESTER	ζ
COMBILIONS OF	ALLENOTERS, IF BUTLE			1	

*See Instructions on Reverse Side

9 1987 DEC

DEC 1 1981