

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL COND. COM. SION
P. O. BOX 1930
HOBBS, NEW MEXICO

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO.

88240 NM-54450

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
H. L. Brown, Jr.

3. ADDRESS OF OPERATOR
P. O. Box 2237, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit H, 1650' FNL & 330' FEL of Sec 28, T-7S, R-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
GL 4060.4'

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal "28" Com

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA
Sec 28, T-7S, R-37E

12. COUNTY OR PARISH
Roosevelt

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Perforating

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

2-11-88: Rig up Schlumberger, ran GR/CCL/Comp Neutron log from WL PBTD 8939-6939'. Rig down Schlumberger.

2-12-88: Rig up pulling unit. Pick up Baker Mod "R" pkr, seating nipple and 281 jts 2-3/8" tbq. Trip in hole to 6320' and set pkr w/1200# comp. SION.

2-14-88: Rig up Schlumberger and perforate from 8898-8910' (24 holes) and 8872-8886' (28 holes).

2-15-88: Flow testing.

18. I hereby certify that the foregoing is true and correct

SIGNED

Gene C. Koser

TITLE

Production Clerk

DATE

2-17-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER

FEB 29 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
MAR 3 - 1988
OCD
HOBBES OFFICE