	. O. BOX 1980 OBBS, NEW ME <b>VIX</b> DEPARTMEN	TEED24STATES	(Other instruct reverse sid RIOR		Budget Bureau M Expires August	31, 1985
		F LAND MANAGEMEN			NM 53389	
APPLICATIO	ON FOR PERMIT	TO DRILL, DEEP	EN, OR PLUG B	ACK	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
<ul><li>1a. TYPE OF WORK</li><li>b. TYPE OF WELL</li></ul>	RILL X	DEEPEN	PLUG BAC	К 🗌	7. UNIT AGREEMENT N	AME
OIL WELL X	GAS WELL OTHER		INGLE MULTIPL	E	8. FARM OR LEASE NAM	(1
2. NAME OF OPERATOR					EL ZORRO FED	DERAL
	Layton Enterp	rises, Inc.			9. WELL NO.	
3. ADDRESS OF OPERAT			70402		3 10. FIELD AND POOL, O	R WILDCAT
4. LOCATION OF WILL	3103 - 79th S (Report location clearly an	s 79423 tate requirements.*)		Allison Penn 11. SEC., T., E., M., OR BLK.		
At surface 1980	'FSL 510'FEL Sec					
At proposed prod.		··,,			AND SURVEY OR AR	E.A.
	same				Sec.25, T8S,	
		AREST TOWN OR POST OFFIC			12. COUNTY OR PARISH	
8 miles e		com Milnesand, N.	M. O. OF ACRES IN LEASE	17 80 6	ROOSEVELT	NM
LOCATION TO PEAR PROPERTY OR LEAS	EST E LINE, FT.	510'	320	TO T	HIS WELL 80 ac.	
	drlg. unit line, if any)		ROPOSED DEPTH	20. ROTA	RY OB CABLE TOOLS	· · · · · · · · · · · · · · · · · · ·
TO NEAREST VELL, DRILLING, COMPLETED, OR APPLIED FOR, ON THIS LEASE, FT.		2640'	9800'	Rotary		7
21. ELEVATIONS (Show whether DF, RT, GR, etc.) 4053 GI					22. APPROX. DATE WORK WILL START July 15, 1988	
23.		PROPOSED CASING AN	D CEMENTING PROGRA	м		
SIZE OF HOLE	SIZE OF CASING	WEIGHT FER FOOT	SETTING DEPTH		QUANTITY OF CEMEN	ŇT
17-1/2'	13-3/8"	54.5#	350'	400s:	x Class C (circ.)	
			4100' 1100s:		x HL + 200sx Cl. C x to isolate all oil, ga	
<u>12-1/4'</u> 7-7/8'	<u> </u>	<u>32#</u> 20#-23#		-	x to isolate al	
7-7/8' Propose: t See <u>Suppl</u> Run 5-'/2 Run tubir IN ABOVE SPACE DESC zone. If proposa is preventer prograph is	5-1/2" 5-1/2" o drill to appro- emental Drilling " production cas ag and stimulate	20#-23# oximately 9800' f g Data for casing sing, perforate f	9800; to test Bough C g and BOP detail favorable zones.	and in s.	x to isolate al and wate termediate form	il oil, g er zones nations.
7-7/8' Propose: See <u>Suppl</u> Run 5- /2 Run tubir IN ABOVE SPACE DESC ZODE. If proposa is preventer program in 24. SIGNED	5-1/2" co drill to appro- emental Drilling 2" production cas ag and stimulate RIBE PROFOSED PROGRAM : J to drill or deepen direction any.	20#-23# pximately 9800' f g Data for casing sing, perforate f as necessary.	9800; to test Bough C g and BOP detail favorable zones.	and in s.	x to isolate al and wate termediate form	ed new product
7-7/8' Propose: See <u>Suppl</u> Run 5- /2 Run tubir IN ABOVE SPACE DESC ZODE. If proposa is preventer program in 24. SIGNED	5-1/2" 5-1/2" o drill to appro- emental Drilling " production cas ag and stimulate	20#-23# pximately 9800' f g Data for casing sing, perforate f as necessary.	9800; to test Bough C g and BOP detail favorable zones. plug back, give data on pr on subsurface locations ar	and in s.	x to isolate al and wate termediate form ductive zone and propose ed and true vertical depti	ed new product
7-7/8' Propose: See <u>Suppl</u> Run 5- /2 Run tubir IN ABOVE SPACE DESC ZODE. If proposa is preventer program in 24. SIGNED	5-1/2" 5-1/2" co drill to appro- emental Drilling 2" production cas ing and stimulate and stimulate RIBE PROPOSED PROGRAM : I to drill or deepen direction any. Cederal or State office use)	20#-23# pximately 9800' for <u>g Data</u> for casing sing, perforate for as necessary. If proposal is to deepen or phally, give pertinent data <u>Support</u> TITLE	9800; to test Bough C g and BOP detail favorable zones. plug back, give data on pr on subsurface locations ar	and in s.	x to isolate al and wate termediate form ductive zone and propose ed and true vertical depti	ed new product
7-7/8' Propose: See <u>Suppl</u> Run 5-'/2 Run tubir IN ABOVE SPACE DESC zone. If proposa is preventer program in 24. SIGNED	5-1/2" co drill to appro- emental Drilling 2" production cas ag and stimulate RIBE PROFOSED PROGRAM : J to drill or deepen direction any.	20#-23# pximately 9800' for <u>g Data</u> for casing sing, perforate for as necessary. If proposal is to deepen or phally, give pertinent data <u>Support</u> TITLE	9800; to test Bough C g and BOP detail favorable zones. plug back, give data on pr on subsurface locations ar President	and in s.	x to isolate al and wate termediate form ductive zone and propose ed and true vertical depti	ed new product

IN ADVANCE. Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States ary false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.