

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-041-20843

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
OGS Operating Co., Inc.

7. Lease Name or Unit Agreement Name

Bilberry

8. Well No.

1

3. Address of Operator
550 W. Texas, Suite 1140, Midland, Texas 79701

9. Pool name or Wildcat
Bluitt (San Andres) Assoc.

4. Well Location
Unit Letter D : 990 Feet From The North Line and 990 Feet From The West Line
Section 14 Township 8-S Range 37-E NMPM Roosevelt County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4020.5' Gr

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|---|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | | CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> | |
| OTHER: <input type="checkbox"/> | | OTHER: <input type="checkbox"/> | |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Spud 12-1/4" hole @ 1:45 p.m. 2-14-89.
- Set 8-5/8" 28# csg @ 365' and cemented with 225 sx Cl C @ 7:00 p.m. 2-14-89.
Cmt circ to surf.
- Install 10" 3000 psi BOP and test to 500 psi.
- Drill 7-7/8" hole to TD @ 4700' on 2-20-89.
- Attempt to run open hole logs but unable to work tools below 1650'.
- Set 4-1/2" 10.5# csg @ 4699' and cemented shoe with 265 sx Cl H-50:50 poz
then cemented DV tool @ 1660' with 235 sx Cl H 65:35 Poz and 100 sx Cl C.
Cement circ to surf @ 12:00 a.m. 2-23-89.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mickey Dolan TITLE Vice President-Drlg & Prod. DATE 4-26-89

TYPE OR PRINT NAME Eddie W. Seay TELEPHONE NO.

(This space for State Use)

APPROVED BY Eddie W. Seay
Oil & Gas Inspector

TITLE Oil & Gas Inspector DATE MAY 1 1989

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 27 1989

**OCD
HOBBS OFFICE**