

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. Fee
7. Unit Agreement Name NONE
8. Farm or Lease Name Ruth Patterson
9. Well No. 1
10. Field and Pool, or Wildcat Wildcat
12. County Chaves

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY
2. Name of Operator TFXACO Inc.
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico
4. Location of Well UNIT LETTER C 660 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 34 TOWNSHIP 6-S RANGE 30-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4235' (D. F.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well has been plugged and abandoned as follows:

1. Spot plug No. 1, 40 Sx. from 8604' to 8704'.
2. Spot plug No. 2, 40 Sx. from 8333' to 8433'.
3. Spot plug No. 3, 40 Sx. from 7688' to 7788'.
4. Spot plug No. 4, 40 Sx. from 7248' to 7348'.
5. Spot plug No. 5, 40 Sx. from 2537' to 2637'.
6. Spot 20 Sx. surface plug inside 9 5/8" O. D. Casing, install 4" marker extending 4' above ground level, location has been cleaned, ready for inspection by the New Mexico Oil Conservation Commission. Plug and abandon complete 12:00 Midnight, February 15, 1961.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Raymond TITLE Assistant District Superintendent

DATE May 5, 1965

APPROVED BY Leslie V. Clement TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: