

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-005-00475
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name C. L. O'Brien
8. Well No. 1
9. Pool name or Wildcat Cato, San Andres Pool #74445

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Primero Operating, Inc.
3. Address of Operator PO Box 1433, Roswell, NM 88202
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>7</u> Township <u>8S</u> Range <u>30E</u> NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4079 DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Plug Back and Pull Casing</u> <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attached well bore diagram.

We propose to set a CIBP @6499' and dump 25 sx cement on top. We will then cut and pull at least 3500' of 7" casing out of the hole. After pulling casing, we will pump a 100' cement plug over the 7" casing stub and tag. After plugging back we will run logs and perforate the San Andres formation and test for commercial gas.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>[Signature]</u>	TITLE <u>President</u>	DATE <u>11-20-00</u>
TYPE OR PRINT NAME <u>Phelps White</u>	TELEPHONE NO. <u>505-622-1001</u>	

(This space for State Use)

APPROVED BY _____	TITLE _____	DATE <u>NOV 30 2000</u>
CONDITIONS OF APPROVAL, IF ANY:		

**Weatherford**

Completion & Oilfield Services

2117 N. French Dr.

Hobbs, NM 88241

COMPANY

PR MERO

PREPARED FOR

NMOCL

TELEPHONE

WELL NAME

C.L. O'Brien #1

FIELD NAME

CATO

COUNTY

CHAVES

STATE

CASING

SIZE

7"

WEIGHT

26 #

GRADE

THREAD

LINER

SIZE

WEIGHT

GRADE

THREAD

TUBING

SIZE

WEIGHT

GRADE

THREAD

DESCRIPTION

990' of 1 3/8" 48# cmt circulator

Tub estimated @ 2380'

(ZONE OF INTEREST)
3000' to 3250'4037' of 2 3/4" 30# w/2645 cmt
To Cement @ 4190'

APPROVED

DATE

POSS. BLD

PERMIT NO. M-45

7539-7823

JSC

6504-26

C-8077

BTD

3013

PREPARED BY

OFFICE 505-622-1001

PHONE 505-393-1717

Alt Hobbs 505-393-1717

405-38-1214