

U. S. DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
P. O. BOX 1980  
HOBBS, NEW MEXICO 88240

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Paloma Resources, Inc.

3. Address and Telephone No.

P.O. Box 1814 Roswell, NM 88202-1814 505-622-0770

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FEL & 660' FSL  
Sec. 29-T15S-R30E

5. Lease Designation and Serial No.

NM-0338A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Peery Fed. #2

9. API Well No.

30-005-00516

10. Field and Pool, or Exploratory Area

Undesignated Morrow

11. County or Parish, State

Chaves Co., New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4-10-94

Operator performed the following work to temporarily abandon the Devonian Formation and re-complete in the Morrow Formation.

Move in and rig up pulling unit. Pull out of hole with tubing and packer. Spot 200 gallons acetic acid from 10020' up to 9900'. Perforate Morrow Formation from 9992'--10006' with 4 JSPF. Go in hole with tubing. Set Guiberson Uni-VI production packer with K-Valve at 10,100'. Cap with 35' sand. Set Guiberson Uni-VI packer with XL on/off tool with 1.81" profile nipple at 9857'. Nipple down BOP and install tree. Rig up and make 5 swab runs. Well kicked off flowing. Flowing on 16/64" choke with 1000# FTP. Rate 1360 mcf/d and 88 bbls condensate. Run in hole with BHP bombs. Shut well in for buildup. Run 4 pt test on 4-23-94. CAOF--2423 mcf/d. Connected to GPM Gas Corporation pipeline.

NOTE: RBP Packer at 10,100' tested to 3500# for 30 min with no leakoff. Plug holding.

14. I hereby certify that the foregoing is true and correct

Signed

*Peter W. Chester*

Title

Agent

ACCEPTED FOR RECORD  
PETER W. CHESTER

Date

5-5-94

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

MAY 23 1994

Date

BUREAU OF LAND MANAGEMENT  
ROSWELL, N.M.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side