

x			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

1961 JUL 24 AM 8:13

Land Office Artesia

Lease No. NM-01171

Unit

JUL 19 1961

O. C. C.
PRESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Lease No. 205289
K. McIntosh Federal

TEXACO Inc. P.O. Box 728
Hobbs, New Mexico July 18, 1961

Well No. 2 is located 330 ft. from N line and 1980 ft. from W line of sec. 34

SE/4, SW/4, Sec. 34
(1/4 Sec. and Sec. No.)

T-15-S
(Twp.)

R-30-E
(Range)

NMPM

(Meridian)

....Undesignated
(Field)

Chaves
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 4008 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD - 3215', PBTD - 3213'

NOTE: Bottom of 4-1/2" casing was cemented with 200 sx, cement was drilled out to plug back depth of 3213', cast iron bridge plug was set at 2750', Spot 2 sx cement on top of bridge plug.

We plan to plug and abandon subject well as follows:

1. Spot 25 sx plug at perforations, 2665' to 2675' and 2713' to 2719'
2. Cut off 4-1/2" OD casing at approximately 500' and recover 500' of casing.
(Top of cement calculated at 515', inside 7-5/8" OD casing set at 640')
3. Spot 15 sx cement plug from 50' below to 50' above top of non-recoverable
4-1/2" OD casing.
4. Spot 15 sx cement plug at the surface inside 7-5/8" OD casing, install
4" marker 4' above ground level as per U.S.G.S. regulations and clean location
for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company TEXACO Inc.

Address P.O. Box 728

Hobbs, New Mexico

J. G. Enevins, Jr.

By

~~Title~~ Assistant District Superintendent