

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-verse side)

Form approved.
Budget Project No. 05-21424.
LEASE REGISTRATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to plug back to a different reservoir.
Use APPLICATION FOR PERMIT for such proposals.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
B. W. P., Inc.

3. ADDRESS OF OPERATOR
1012 Alpine, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1300' FNL & 660' FWL, Sec. 7, T-7-S, R-31-E.
1980

14. PERMIT NO.
14 DE

15. ELEVATIONS (Indicate whether DS, RT, OR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

5. LEASE REGISTRATION AND SERIAL NO.
0-1906-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
General American Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT
Long Mission Indian

11. SEC., T., R., OR S.W., OR S.E., AND SURVEY OR AREA
7-7-31

12. COUNTY OR PARISH
Chaves

13. STATE
New Mexico

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREATMENT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Include name of pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give magnetic location and measured and true vertical depths for all markers and bottom perforations to this work.)

(NOTE: Report results of multiple completion or well Completion or Recompletion Report and Log form.)

Abandonment Operations to begin on or about February 1, 1971.
Well is classified as non-commercial.

Procedure: Cement Plug (100') at 8396 to 8423 in 5" Casing. (12 ex.)
Cut and recover approximately 6000' of 5" Casing. Cement Plug (100') 50' inside 5" and 50' in 7 7/8 O.H. (21 ex.)
Cement Plug in 7 7/8 O.H. (100') spotted midway between 8 5/8 Shoes @ 3124' and 5" Casing Cut. (31 ex.)
Cement Plug (100') at 5/8 Casing Seat 50' inside 8 5/8 and 50' outside in 7 7/8 O.H. (31 ex.)
Cut and recover approximately 1500' of 8 5/8 Casing. Cement Plug (100') at 5/8 Casing cut; 50' inside of 8 5/8 and 50' in 11" O.H. (46 ex.)
Cement Plug (100') 13" Casing seat @ 249'. 50' in 11" O.H. and 50' inside 13" Casing. (70 ex.)
Cement Plug Surface to 20' w/ 4" Marker (16 ex.)
Cement Plug between plugs.

Equipment to be moved out and pits filled, etc.

18. I hereby certify that the foregoing is true and correct

SIGNED AND SWEAR TO
JAN 22 1971

TITLE

MANAGER

DATE JANUARY 20, 1971

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

JAN 21 1971

DATE

R. L. BEEKMAN
ACTING DISTRICT ENGINEER

U.S. GEOLOGICAL SURVEY
ALBUQUERQUE OFFICE

*See Instructions on Reverse Side

M. M. D. C. C. COPY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different stratum.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. NAME OF OPERATOR
B. W. P. Inc.

2. ADDRESS OF OPERATOR
1015 Alameda, Midland, Texas 79701

3. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
Give also space if below.)
1500' FWL & 600' FWL, Sec. 7, T-7-S, R-21-E.

4. PERMIT NO.
1480

5. RELATIONS (Show whether on, in, or off)
STATE OF TEXAS

6. COUNTY OF WISCONSIN
CHANDLER

7. COUNTY OF TEXAS
MIDLAND

8. FIELD AND FOOT OF PROJECT
1000' FWL & 600' FWL

9. NAME OF STATE NAME
General American (Federal)

10. UNIT OF MEASUREMENT NAME
Feet

11. DATE OF REPORT
1-2-63

12. DATE OF PERMIT
1-2-63

13. DATE OF REPORT
1-2-63

14. DATE OF PERMIT
1-2-63

Check appropriate box to indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SAMPLES
EXPOSED TO AIR
SHOOT OF ACIDIZING
REPAIR WELL
(Other)

CHANGE PLANS
ABANDON
MULTIPLE COMPLETS
FILL OR ALTER CASING
(Other)

SHOOTING OR ACIDIZING
REPAIR TREATMENT
WATER SHUT-OFF
(Other)

ABANDONMENT
STIMULATING CASING
STIMULATING WELL
(Other)

15. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent data, including estimated date of starting and completion of work. If well is abandoned, clearly state reasons and measures taken to prevent pollution of the water.)

Abandonment Operations to begin on or about February 1, 1971.
Well is completed as non-commercial.

Procedure: Cement plug (100') section part. 8 3/8" to 8 1/2" in 2" casing.
Cut and recover approximately 6000' of 2" casing.
Plug (100') 20' inside 2" and 20' in 2 7/8 O.H.
Cement plug in 2 7/8 O.H. (100') section midway between
8 3/8" and 8 1/2" and 2" casing cut.
Cement plug (100') at 8 3/8" casing seat 20' inside 8 3/8"
20' outside in 2 7/8 O.H.
Cut and recover approximately 1200' of 8 3/8" casing. Cement
plug (100') 2 7/8 casing out; 20' inside at 8 3/8" and
20' in 11" O.H.
Cement plug (100') 11 3/8" casing seat 20' in 11"
20' outside to 20' in 4" casing.
equipped with two 11 3/8" casing plugs.

Equipment to be moved out and site filled, etc.

RECEIVED
JAN 25 1971
CONSERVATION COMM.

RECEIVED

JAN 25 1971

O. C. C.
ARTESIA, OFFICE

See instructions on reverse side