

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPI
(Other instructions
verse side)

TE*
re-

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

~~Federal 03985-A~~

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
~~General American Fed.~~
~~KIMMEXXAMMIX~~

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC. T. R., M., OR BLK. AND
SURVEY OR AREA

12. COUNTY OR PARISH 13. STATE

~~Chaves~~

~~New Mexico~~

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back (for a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

APR 23 12 00 PM '69

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

~~B. W. P., Inc.~~

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

~~1012 Alpine, Midland, Texas~~

~~660' FWL & 1980' FNL Sec. 7, 7S, 31E~~

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

~~4314 DF~~

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

~~Perforating & Acidizing~~

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

3-25-69 Perforated, 2 shots per foot, Schlumberger 0.45 M3

Mississippi

8396 to 8403

8410 to 8412.5

8421 to 8423.5 Total 24 Holes

3-26-69 Acidized under Guiberson Packer set @ 8330'.

Perforations 8396 to 8424

Dowell, 4000 gpl. 24% and 3000 Gal. 5%, 20 Ball Sealers.

**Average Inj. Rate 4.0 BPM, Max. Pressure 3800#, Avg. Pressure 3500#,
Final Pressure 3450#. SIP Immediate 1900#, 10 min. SIP 1200#.**

Flowed back to clean up.

RECEIVED

RECEIVED
APR 17 1969
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Manager

DATE

4-16-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.