DISTRIBUTION ANTA FE		Form C -103
		Supersedes Old
	NEW MEXICO OIL CONSERVATION COMMISSION . C. G.	C-102 and C-103 Effective 1-1-65
ILE		P110001AB 1-1-02
.s.g.s.	hand to the switch	5a. Indicate Type of Lease
AND OFFICE	─ Jun 18 11 55 AM '66	State Fee
PERATOR		5. State Oil & Gas Lease No.
		E-6955
SLIN	DRY NOTICES AND REPORTS ON WELLS	mminimum
(DO NOT USE THIS FORM FOR USE "APPLI	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
		7. Unit Agreement Name
OIL GAS WELL	OTHER-]
Name of Operator		8. Farm or Lease Name
Morris R. Ar	TEWO11	Hunt State "C"
Address of Operator	14A	9. Well No.
r. U. Box 20	10, Hobbs, New Mexico	1. 1
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE South LINE AND 660 FEET FRO	1141 4
1	FEET FROM THE STATE LINE AND FEET FROM	
THE East LINE, SE	CTION 16 TOWNSHIP 118 RANGE 31E NMPP	
	TOWNSHIP RANGE NMP	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4477 D.F.	
Chan		Chaves \\\\\\\
MOTICE	k Appropriate Box To Indicate Nature of Notice, Report or O	
NOTICE OF	SUBSEQUEN	IT REPORT OF:
BEARL BENEFIT		
RFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
MPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
LL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
OTHER	OTHER	
OTHER		
	I I	
,	Operations (Clearly state all pertinent details, and give pertinent dates, includin	g estimated date of starting any propose
This well was p 1. Hole leaded 2. 10 sxs cemen 3. Gut and record 4. 20 sxs. cemen 5. 20 sxs. cemen 6. 20 sxs. cemen 7. 20 sxs. cemen 8. 25 sxs. cemen 9. 10 sxs. cemen	lugged and abandoned as follows: with heavy mud. t 11,000' across perforations vered 9920' of 3-1/2" casing. nt 9935'. Start of 3-1/2" casing. nt 7200' nt 6350'	

CONDITIONS OF APPROVAL, IF ANY: