

COPIES RECEIVED	
TRIBUTION	
FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-399	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name North Caprock Queen Unit #2
2. Name of Operator Anadarko Production Company		8. Farm or Lease Name Tract #26
3. Address of Operator P. O. Box 647 Artesia, New Mexico 88210		9. Well No. 4
4. Location of Well UNIT LETTER B , 990 FEET FROM THE North LINE AND 1652 FEET FROM THE East LINE, SECTION 11 TOWNSHIP 13S RANGE 31E NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4411 GL		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 7" Abandonment plug at 3000'. Pumped 40 sacks cement above plug. Pumped 25 sacks cement from 1650' to 1750'. Cut off oil string at 854'. Pumped 40 sacks cement from 800' to 900'. Pumped 40 sacks cement from 210' to 310'. Ten sacks cement at surface with heavy mud between all plugs. Set surface marker and cleaned location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. D. Munger (by SJ) TITLE Agent DATE 5/10/74

Orig. Signed by
John Ryan
Geologist

APPROVED BY _____ TITLE _____ DATE MAY 13 1976

CONDITIONS OF APPROVAL, IF ANY: