NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature	of Notice by Checkin	ng Below	
Notice of Intention to Change Plans	Notice of Intent Temporarily Aba	TION TO ANDON WELL	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intent to Plug Back	rion	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intent to Acidize	TION	Nomen on L	
Notice of Intention to Gun Perforate	Notice of Intent (Other)	TION	Notice of Intention (Other)	· ·
OIL CONSERVATION COM SANTA FE, NEW MEXICO		New Mexico (Place)	March 10, 19	55
Gentlemen:			(Date)	
Following is a Notice of In	stention to do certain work as desc	ribed below at the	N. M. State "H" a/o	_1
Texas Pacific Compa	1 and Oil Company		Well No2 in.	
1/4 SI 1/4 of	Sec	R 31 R NAC	PM., Drickey Queen	(Unit)
Chaves		,IN M	PM.,MELEKSY (MAG)	PoPo
	FULL DETAILS OF P (FOLLOW INSTRUCTIONS II	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
10000 g	FULL DETAILS OF P (FOLLOW INSTRUCTIONS II Clean out open hele,	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
10000 g	Clean out open hele.	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
19000 g	Clean out open hele.	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
10000 g	Clean out open hele.	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
3.0000 g	Clean out open hele.	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
3.0000 g	Clean out open hele.	N THE RULES AN 3080! - 3090!	D REGULATIONS)	
pproved	Clean out open hele.	N THE RULES AN 3060' 3090', 0# of sand.	D REGULATIONS)	
Decoo go	Clean out open hele,	N THE RULES AN 3060' 3090', 0# of sand.	ific Coal and Oil Come	
pproved	Clean out open hele,	Texas Pac By Position Pistr	ific Coal and Oil Come	
oprovedecept as follows:	Clean out open hele,	N THE RULES AN 3060' - 3090', Of of sand. By	ific Coal and Oil Company or Operator Lucula	D: