| NO. OF COPIES RECEIVED | 15 | |
|-------------------------------------|--|--|
| SICT DISTINCT | | Form C-103 |
| DISTRIBUTION | | Supersedes Old C-102 and C-103 |
| SANTA FE FILE | NEW MEXICO OIL CONSERVATION COMMISSION | Effective 1-1-65 |
| U.S.G.S. | | |
| LAND OFFICE | | 5a. Indicate Type of Lease |
| OPERATOR | | State Fee. |
| OF ERRIOR | | 5. State Oil & Gas Lease No. Patent |
| SLIA | IDDA NOTICES AND BEDODES ON MELLS | |
| (DO NOT USE THIS FORM FOR USE "APPL | IDRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) | |
| | (OKIN C-101) FOR SOCH PROPOSALS.) | 7. Unit Agreement Name |
| OIL GAS WELL WELL | OTHER- | 1 |
| 2. Name of Operator | | 8. Farm or Lease Name |
| Union Cil of Ca | Lifornia | |
| 3. Address of Operator | | 5. Caprock Oseen Unit 9. Well No. |
| 500 N. Marinafeld - Midland, Temas | | TLET 14.6 0-0 |
| 4. Location of Well | | 10. Field and Pool, or Wildcat |
| UNIT LETTER | 660 FEET FROM THE W LINE AND 1980 FEET FRO | 8. Caprock Queen Unit |
| , | LINE AND FEET FRO | M |
| THELINE. SE | CTION TOWNSHIP RANGE NMPP | |
| | NMP | «(|
| | 15. Elevation (Show whether DF, RT, GR, etc.) | 12. County |
| | ()\\\\\\\ GL 4450* | Chaves |
| Unec NOTICE OF | k Appropriate Box To Indicate Nature of Notice, Report or O | |
| | SUBSEQUEN | NT REPORT OF: |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | _ |
| TEMPORARILY ABANDON | | ALTERING CASING |
| PUL'L OR ALTER CASING | COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JOB | PLUG AND ABANDONMENT |
| | OTHER_ | ├ |
| OTHER | | |
| 12 D | | |
| work) SEE RULE 1103. | Operations (Clearly state all pertinent details, and give pertinent dates, includin | g estimated date of starting any propose |
| | | |
| Flugging Procedu | res Belov: | |
| | | |
| 1. 8 5/8" @ 309 | ¥/150 8x. | |
| 2. 7" @ 3096' W | 100 &. | |
| 3. Perf. 6 Open | 300K1 - 210K1 | |
| | 20 July 32 Mg | |
| | | |
| Nug A - 100 | Hug & Perf. | |
| Nug A - 100 | | |
| Plus A - 100 Plus A - 20 | Hug & Perf. Plug & Surface | |
| Nug A - 100 | Hug & Perf. Plug & Surface | |
| Plus #2 - 20 | * Fing & Ferf. * Fing & Surface Tubing | |

G

Geologist

CONDITIONS OF APPROVAL, IF AN

APR 4.1875

CAL CONSTRUMENT OF COMM.