

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. LC 000000

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name S. Caprock Queen Unit
2. Name of Operator Union Oil of California	8. Farm or Lease Name S. Caprock Queen Unit
3. Address of Operator Box A. Warrenfield - Midland, Texas	9. Well No. 1-03, H-3, Sec. 8
4. Location of Well UNIT LETTER C 1960 FEET FROM THE W LINE AND 660 FEET FROM N 0 15 S 31 E THE _____ LINE, SECTION _____ TOWNSHIP _____ RANGE _____ NMPM.	10. Field and Pool, or Wildcat S. Caprock Queen Unit
15. Elevation (Show whether DF, RT, GR, etc.) GL 4454	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 8 5/8" - 311'
2. 5" - 3119' w/175 ex.
3. Perf. Open - 311' - 312'
 - plug #1 - 100' plug & perf.
 - plug #2 - 100' plug & Stub of 5"
 - plug #3 - 10' plug in and out of surface
 - plug #4 - 20' plug & surface

Establish Dry Hole Marker

H. D. Uden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Agent for Union Oil

SIGNED H. D. Uden TITLE of California DATE June 8, 1971

APPROVED BY [Signature] TITLE SUPERVISOR DISTRICT I DATE JUN 28 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 21 1971

OIL CONSERVATION COMM.
HOBBES, W. M.