

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

So. Caprock Queen Unit

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Chaves County, New Mexico

7. UNIT AGREEMENT NAME

So. Caprock Queen Unit

8. FARM OR LEASE NAME

S.C.R.Q. Unit

9. WELL NO.

6 - Tr. 6

10. FIELD AND POOL, OR WILDCAT

S. Caprock Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17

12. COUNTY OR PARISH

Chaves

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME So. Caprock Queen Unit	
2. NAME OF OPERATOR Union Oil of California		8. FARM OR LEASE NAME S.C.R.Q. Unit	
3. ADDRESS OF OPERATOR 500 N. Marienfeld - Midland, Texas 79701		9. WELL NO. 6 - Tr. 6	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL, 1900' FNL, Sec. 17, Township 15 S., Rng. 31 E		10. FIELD AND POOL, OR WILDCAT S. Caprock Queen	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) LF 4455'	
		12. COUNTY OR PARISH Chaves	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. 8 5/8" @ 304' - Circ.

2. 5 1/2" @ 3131' 4/400 Sx.

3. Perf. 3112' - 3122'

Plug No. 1 - 25 Sx. @ 3100'

Plug No. 2 - 25 Sx. @ Stub of 5 1/2"

Plug No. 3 - 35 Sx. @ Base of Surface 304'

Plug No. 4 - 5 Sx. @ Surface

HEAVY MUD MUST BE PLACED
BETWEEN ALL PLUGS.

RECEIVED

APR 23 1971

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent for Union Oil

of California

DATE

April 26, 1971

(This space for Federal or state office use)

APPROVED BY

TITLE

DATE

COMMITTEE OF APPROVAL, IF ANY:

APPROVED

APR 29 1971

R. L. BECKMAN

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1963-O-685229

847-485

RECEIVED

APR 30 1971

O. C. C.
ARTESIA, OFFICE

RECEIVED

MAY 6 1971

OIL CONSERVATION COMM.
HOBBS, N. M.

