

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

B 8459

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name S. Caprock Queen
2. Name of Operator Union Oil of California	8. Farm or Lease Name S. Caprock Queen
3. Address of Operator 500 N. Marienfeld - Midland, Texas	9. Well No. T-18-W-8, Sec. 19
4. Location of Well UNIT LETTER H 1980 FEET FROM THE N LINE AND 660 FEET FROM THE E LINE, SECTION 19 TOWNSHIP 15 S RANGE 31 E NMPM.	10. Field and Pool, or Wildcat S. Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) GL 4439	12. County Chaves

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input checked="" type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 7 5/8" @ 304' W/300 Sx.
2. 4 1/2" @ 3118' W/75 Sx.
3. Perf. @ Open Hole 3118' - 3136'

Plug #1 - 20 Sx. @ 3100'
Plug #2 - 4 1/2" @ Stub W/25 Sx.
Plug #3 - 35 Sx. @ Base of Surface 304'
Plug #4 - 5 Sx. @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Agent for Union Oil
of California

SIGNED H. D. Oden

TITLE

DATE

July 20, 1971

APPROVED BY [Signature]

TITLE

DATE

SUPERVISOR DISTRICT I

JUL 23 1971

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 22 1971

OIL CONSERVATION COMM.
WASH., D.C.