

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 8663	
7. Unit Agreement Name	
S. Caprock Queen Unit	
8. Farm or Lease Name	
S. Caprock Queen Unit	
9. Well No.	
T-47, W-16, Sec. 19	
10. Field and Pool, or Wildcat	
S. Caprock Queen Unit	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Union Oil of California
3. Address of Operator 500 N. Marienfeld - Midland, Texas
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>S</u> LINE AND <u>660</u> FEET FROM THE <u>E</u> LINE, SECTION <u>19</u> TOWNSHIP <u>15 S</u> RANGE <u>31 E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) GL 4437

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 9 5/8" @ 307' Circ.
2. 5" @ 3163' W/175 Sx.
3. erf. @ 3128' - 3144'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 5 Sx. @ Surface

Recovered 3000' Tubing

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden TITLE Agent for Union Oil of California DATE August 12, 1971

APPROVED BY Nathan E. Clegg TITLE Oil and Gas Division DATE August 12, 1971
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 4 1975

OIL CONSERVATION COMM.
DALLAS, N. M.

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E 8663	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name S. Caprock Queen
2. Name of Operator Union Oil of California		8. Farm or Lease Name S. Caprock Queen
3. Address of Operator 500 N. Marienfeld - Midland, Texas		9. Well No. T-47, W-16, Sec. 19
4. Location of Well UNIT LETTER P 660 FEET FROM THE S LINE AND 660 FEET FROM THE E LINE, SECTION 19 TOWNSHIP 15 S RANGE 31 E NMPM.		10. Field and Pool, or Wildcat S. Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) OL 4437		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugging Procedures Below:

1. 9 5/8" @ 307' Circ.
2. 5 1/2" @ 3163' W/175 Sx.
3. Perf. @ 3128' - 3144'

Plug #1 - 25 Sx. @ 3100'
Plug #2 - 25 Sx. @ 5 1/2" Stub
Plug #3 - 35 Sx. @ Base of Surface 307'
Plug #4 - 5 Sx. @ Surface

Establish Dry Hole Marker

H. D. Oden, Inc.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. D. Oden	TITLE Agent for Union Oil of California	DATE June 20, 1971
APPROVED BY [Signature]	TITLE SUPERVISOR DISTRICT I	DATE JUL 23 1971
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JUL 02 1971

OIL CONSERVATION COMM.
HISCO, AT HQ.